Chicagoland Roofing Council

SAFETY DASHBOARD

Contractor	All Sealants, Inc.	Surveyed by	Jim Meegan
Date	8/02/2022 9:29 AM	Foremen	Hector Pantoja
Project	166 N Aberdeen St	Project Address	166 N Aberdeen St Chicago,IL
Site Conditions			
Site Activity	Hot rubberized asphalt		
Notes	Discussed below concerns with Hector		

Comments on Project Conditions

Description of Condition
Access via scaffold stair tower; guardrail protection provided adjacent to access point
Crew protected by parapet walls > 39” high in most areas
Guardrail protection provided along edges
Propane secured and maintained at least 10 feet from kettle burners
Fire extinguishers available and in good condition; discussed locating others
Kettle wheels chocked to prevent movement
Drinking water available on the roof
Long-sleeve protection, hardhats, gloves, and safety glasses worn by all

Recommendations

Description and Recommended Action
Face shield should be utilized at kettle
Gloves should be appropriate for the hazard
Additional rebar protection is necessary

Weather Conditions

Clouds - broken clouds; Wind from 94 @1.01mph; Temp: 78.21(f); Low: 73.08 - High: 80.65; Humidity: 62%

Documentation of work conditions and recommendations are based on information available at the time of this inspection report completion. This report does not imply or guarantee full compliance with local, state or federal regulations which may be applicable to such work practices and conditions. This report does not signify or imply that other hazards do not exist at this work location.

All Sealants, Inc.

166 N Aberdeen St | 8/02/2022 | 9:29 AM

Access via scaffold stair tower; guardrail protection provided adjacent to access point

All Sealants, Inc.

166 N Aberdeen St | 8/02/2022 | 9:29 AM

Crew protected by parapet walls > 39” high in most areas

All Sealants, Inc.

166 N Aberdeen St | 8/02/2022 | 9:29 AM

Guardrail protection provided along edges

All Sealants, Inc.

166 N Aberdeen St | 8/02/2022 | 9:29 AM

Propane secured and maintained at least 10 feet from kettle burners

All Sealants, Inc.

166 N Aberdeen St | 8/02/2022 | 9:29 AM

Fire extinguishers available and in good condition; discussed locating others

All Sealants, Inc.

166 N Aberdeen St | 8/02/2022 | 9:29 AM

Drinking water available on the roof

All Sealants, Inc.

166 N Aberdeen St | 8/02/2022 | 9:29 AM

Drinking water available on the roof

All Sealants, Inc.

166 N Aberdeen St | 8/02/2022 | 9:29 AM

Long-sleeve protection, hardhats, gloves, and safety glasses worn by all

All Sealants, Inc.

166 N Aberdeen St | 8/02/2022 | 9:29 AM

Face shield should be utilized at kettle

All Sealants, Inc.

166 N Aberdeen St | 8/02/2022 | 9:29 AM

Gloves should be appropriate for the hazard

All Sealants, Inc.

166 N Aberdeen St | 8/02/2022 | 9:29 AM

Additional rebar protection is necessary