Chicagoland Roofing Council

SAFETY DASHBOARD

Contractor	All Sealants, Inc.	Surveyed by	Jim Meegan
Date	7/15/2025 10:33 AM	Foremen	Juan Pablo Sanchez
Project	Hollywood Casino	Project Address	Church Rd Aurora,IL 60502
Site Conditions			
Site Activity	Preparing to relocate material		
Notes			

Comments on Project Conditions

Description of Condition
Access to various levels via stairway
Use of hardhats, safety glasses, high-vis
Blasting machine equipped with dust collection system / HEPA filtration; discussed OSHA silica exposure monitoring requirements
Steel shot used for blasting media
Containers of hazardous chemicals are labeled
Fire extinguishers available and in good condition

Recommendations

Description and Recommended Action
No Comments Reported

Weather Conditions

Haze - haze; Wind from 170 @9.22 mph - recorded @ 7/15/2025 11:18 AM

Documentation of work conditions and recommendations are based on information available at the time of this inspection report completion. This report does not imply or guarantee full compliance with local, state or federal regulations which may be applicable to such work practices and conditions. This report does not signify or imply that other hazards do not exist at this work location.



All Sealants, Inc.

Hollywood Casino | 7/15/2025 | 10:33 AM

Access to various levels via stairway

All Sealants, Inc.

Hollywood Casino | 7/15/2025 | 10:33 AM

Use of hardhats, safety glasses, high-vis

All Sealants, Inc.

Hollywood Casino | 7/15/2025 | 10:33 AM

Blasting machine equipped with dust collection system / HEPA filtration; discussed OSHA silica exposure monitoring requirements

All Sealants, Inc.

Hollywood Casino	7/15/2025	10:33 AM

Steel shot used for blasting media



All Sealants, Inc.

Hollywood Casino | 7/15/2025 | 10:33 AM

Containers of hazardous chemicals are labeled

All Sealants, Inc.

Hollywood Casino | 7/15/2025 | 10:33 AM

Fire extinguishers available and in good condition