Chicagoland Roofing Council

SAFETY DASHBOARD

Contractor	All Sealants, Inc.	Surveyed by	Jim Meegan
Date	5/19/2025 8:53 AM	Foremen	Josh Delarosa
Project	1600 N Fremont	Project Address	1601–1611 N Clybourn Ave Chicago,IL 60642
Site Conditions			
Site Activity	Air barrier		
Notes			

Comments on Project Conditions

Description of Condition
Work performed from ground level; high-visibility clothing worn
Use of hardhats, safety glasses, gloves
Containers of hazardous chemicals are labeled
Gloves and protective clothing worn
Swing radius of adjacent telehandler is barricaded

Recommendations

Description and Recommended Action
No Comments Reported

Weather Conditions

Clouds - overcast clouds; Wind from 72 @5.99 mph - recorded @ 5/19/2025 8:54 AM

Documentation of work conditions and recommendations are based on information available at the time of this inspection report completion. This report does not imply or guarantee full compliance with local, state or federal regulations which may be applicable to such work practices and conditions. This report does not signify or imply that other hazards do not exist at this work location.

Reviewed w/ Hector

All Sealants, Inc.

1600 N Fremont 5/19/2025 8:53 AM

Work performed from ground level; high-visibility clothing worn



All Sealants, Inc.

1600 N Fremont | 5/19/2025 | 8:53 AM

Use of hardhats, safety glasses, gloves



All Sealants, Inc.

1600 N Fremont | 5/19/2025 | 8:53 AM

Containers of hazardous chemicals are labeled

All Sealants, Inc.

1600 N Fremont | 5/19/2025 | 8:53 AM

Gloves and protective clothing worn

All Sealants, Inc.

1600 N Fremont | 5/19/2025 | 8:53 AM

Swing radius of adjacent telehandler is barricaded



All Sealants, Inc.

1600 N Fremont | 5/19/2025 | 8:53 AM

Swing radius of adjacent telehandler is barricaded